LONE BUTTE DEVELOPMENT CORPORATION 2021 CONSUMER CONFIDENCE REPORT WATER SYSTEM NUMBER-0400345															
								Microbiological	Sample	Violation	Level	Unit	MCLG	MCL	Likely
								Contaminants	Date	Y/N	Detected	Measure			Source
Total Coliform Bacteria	01/01/21-12/31/21	NO	0		0	0	Naturally present in the environment								
Fecal Coliform	01/01/21-12/31/21	NO	0		0	0	Human or animal waste								
NOTE: Bacteria samples are collected monthly.															
Lead	90th Percentile not to exceed AL				0.015		Corrosion of household plumbing system								
Sampling Results	Total number of samples collected		20				Erosion of natural deposits. Sampled every 3 years								
9/10/2021	90th Percentile (ppm)		ND												
Number of sampling sites which exceeded the Action Level (AL)			0												
Copper	90th Percentile not to exceed AL				1.3		Corrosion of household plumbing system								
Sampling Results	Total number of samples collected		20				Erosion of natural deposits. Leaching								
9/10/2021	90th Percentile (ppm)		0.037				from wood preservations. Sampled every 3 years								
Number of sampling sites which exceeded the Action Level (AL)			0												
Inorganic															
Contaminants															
Alkalinity	5/20/2021	No	89	ppm	none	none	Geological								
Arsenic	5/3/2019	No	5.9	ppm	none	0.01	Geological, pesticide residues								
Asbestos	5/24/2016	No	<0.2	Mfl	7	7	Decay of asbestos cement water mains								
Barium	5/15/2019	No	110	ppm	2	2	Geological, pesticide residues								
Calcium	5/20/2021	No	53	ppm	n/a	n/a	Discharge from metal refineries								
Chromium	5/3/2019	No	9	ppm	0.1	0.1	Discharge from steel & pulp Mills; Erosion of natural deposits								
Hardness	5/20/2021	No	250	ppm	n/a	n/a	Geological, Corrosion of galvanized pipes								
Magnesium	5/20/2021	No	29	ppm	n/a	n/a	Geological								
Fluoride	8/5/2021	No	ND	ppm	4	4	Geological, toothpaste, water additives								
pΗ	5/20/2021	No	8.1	ppm	n/a	n/a	Geological								
Nitrate	8/5/2021	No	1.1	ppm	10	10	Fertilizer,sewage,feedlots,geological								
Total Dissolved Solids	5/20/2021	No	720	ppm	748	748	Geological								
DISINFECTION BY-PRODUCTS	(TTHMs)														
Total Trihalomethanes	8/9/2021	No	0.009	ppb	0	0.08	By-product of drinking water chlorination								

Lone Butte Development Corporation receives its drinking water from two (2) wells located within the park. Both wells are 950' deep and draw from the lower Alluvial unit of Gila River Indian Community Basin "A". As it is pumped, the drinking water is disinfected with Sodium Hypochlc Hypochlorite and stored in (3) storage tanks (1/2 million gallon, 3/4 million gallon and a 1 million gallon). From there it is distributed to the system as needed.

Lone Butte Development Corporation drinking water is below all MCL set by E.P.A and is in compliance and up to date with all testing for drinking water.

Water systems that exceed a MCL, or meet action levels are required to give the health effects of the contaminant that is testing high. Since Lone Butte is in compliance we are not required to report such information. Lone Butte does feel that we should give some health effects of a few contaminants to provide its customers with valuable information that they may use in the future.

DEFINITIONS AND TERMS

MCL--The highest level of a contaminant allowed in drinking water

MCLG-- The level of a contaminant at which there is no known or expected health risk.

Action level--The concentration of a contaminant which, if exceeded, triggers treatment or other requirements

ppm-- Parts per million, or milligrams per liter (mg/l)

pCi/L-- Picocuries per liter, (a measure of radioactivity) na-- Not applicable

INORGANIC CONTAMINANTS

Arsenic. Some people who drink water containing arsenic in excess of the MCL over many years could experience skin damage or problems with their circulatory system, and may have an increased risk of getting cancer,

Nitrate. Infants below the age of six months who drink water containing nitrate in the excess of the MCL could become seriously ill and, if untreated, may die. Symptoms include shortness of breath and blue-baby syndrome.

MICROBIOLOGICAL CONTAMINANTS

Total Coliforms. Coliforms are bacteria which are naturally present in the environment and are used as an indicator that other, potentially harmful bacteria may be present.

Fecal Coliform / E. Coli. Fecal coliforms and E. coli are bacteria whose presence indicates that the water may be contaminated with human or animal waste. Microbes in these wastes can cause short-term effects, such as diarrhea, cramps, nausea, headaches, or other symptoms. They pose special health risk for infants, young children, and people with severely compromised immune systems.

DISINFECTION BY-PRODUCTS

TTHM'S (Total Trihalomethanes). Some people who drink water containing triahalomethanes in excess of the MCL over many years may experience problems with their liver, kidneys, or central nervous system, and may have an increased risk of developing cancer.

If you have any questions please contact the Jim Dean, Lone Butte Operations Supervisor at 520-796-5644. Additionally you can contact the USEPA hotline at 1-800-426-4791.